Amendments to the Specification:

Please amend paragraph [0027] as follows:

[0027] Fig. 2 shows an exploded side view of a portion of the hollow profile in combination with an associated socket profile as part of a connecting member, said socket profile being shown in section;